

CLASSIFIED MESSAGE

DATE

0906Z 09 SEP 63

S E C R E T

ROUTING

1	2	3	4	5	6
	COMM			OD	
	DEA				

TO : DIRECTOR

FROM :

ACTION:

INFO : OSA 1-15

Mission 6066

ROUTINE

EDD  
WER  
RDO  
RLP  
KB  
SHI  
PGS

IN 90462

TOR: 1156Z 09 SEP 63

TO

INFO

CITE

0350

REF 2600

TECH ANALYSIS OF DUPE OF MISSION 6066

1. TRACK-1 RCVR B-SCAN APPEARS NORMAL EXCEPT FOR BEGINNING AND END OF MISSION. NUMEROUS INTERCEPTS AT BOTH THESE POINTS, SWEEP AND RETURN TIME APPEARED NORMAL ON SCOPE, BUT WAS SLIGHTLY AFFECTED BY SPURS.

TRACK-2 RCVR A-THIS RCVR HAD A FAILURE IN THAT THE MARKER PULSES PRODUCED WERE DISTORTED. NUMEROUS INTERCEPTS AT BEGINNING AND END OF MISSION. CAN UNDERSTAND ODINCH DIFFICULTY IN FREQ READOUT DUE TO DISTORTION OF MARKER PULSES.

TRACK-3 RCVR C-SCAN APPEARS NORMAL, 3.5 MS SWEEP, 3.0 MS RETURN, ACTIVITY MUCH THE SAME AS TRACK-1.

2. THE SYSTEM FLOWN ON THIS MISSION (SER 5) SCHEDULED TO BE LOADED ON NEXT TRAINING FLIGHT. WILL CHECK TAPE AND NOTIFY HQS OF ANY DEVELOPMENTS.

END OF MESSAGE

25 YEAR RE-REVIEW

S E C R E T

GROUP 1  
Excluded from automatic  
downgrading and  
declassification